

**National Transportation Safety Board
Washington, DC 20594**

Brief of Accident

Adopted 03/31/1998

DCA96MA068 File No. 1696	07/06/1996	PENSACOLA, FL	Aircraft Reg No. N927DA	Time (Local): 14:24 CDT		
Make/Model:	McDonnell Douglas / MD-88			Fatal	Serious	Minor/None
Engine Make/Model:	P&W / JT8D-219		Crew	0	0	5
Aircraft Damage:	Substantial		Pass	2	2	133
Number of Engines:	2					
Operating Certificate(s):	Flag Carrier/Domestic					
Name of Carrier:	DELTA AIR LINES INC					
Type of Flight Operation:	Scheduled; Domestic; Passenger Only					
Reg. Flight Conducted Under:	Part 121: Air Carrier					
Last Depart. Point:	Same as Accident/Incident Location			Condition of Light:	Day	
Destination:	ATLANTA, GA			Weather Info Src:	Weather Observation Facility	
Airport Proximity:	On Airport			Basic Weather:	Visual Conditions	
Airport Name:	PENSACOLA REGIONAL			Lowest Ceiling:	Unknown	
Runway Identification:	17			Visibility:	7.00 SM	
Runway Length/Width (Ft):	7002 / 150			Wind Dir/Speed:	210 / 012 Kts	
Runway Surface:	Asphalt			Temperature (°C):	32	
Runway Surface Condition:	Dry			Precip/Obscuration:		
Pilot-in-Command	Age: 40			Flight Time (Hours)		
Certificate(s)/Rating(s)				Total All Aircraft:	12000	
Airline Transport; Multi-engine Land				Last 90 Days:	142	
Instrument Ratings				Total Make/Model:	2300	
Airplane				Total Instrument Time:	UnK/Nr	

During the initial part of its takeoff roll, the airplane experienced an engine failure. Uncontained engine debris from the front compressor front hub (fan hub) of the #1 (left) engine penetrated the left aft fuselage. Two passengers were killed and two others were seriously injured. The takeoff was rejected, and the airplane was stopped on the runway. The fan hub had fractured through a tierod hole and blade slot. Some form of drill breakage or drill breakdown, combined with localized loss of coolant and chip packing, had occurred during the drilling process, creating an altered microstructure and ladder cracking in the fan hub. Drilling damage extended much deeper into hole sidewall material than previously anticipated by P & W. Fatigue cracks initiated from the ladder cracking in the tierod hole and began propagating almost immediately after the hub was put into service in 1990. The crack was large enough to have been detectable during the last fluorescent penetrant inspection at Delta. Delta's nondetection of the crack was caused either by a failure of the cleaning and fluorescent penetrant inspection processing, a failure of the inspector to detect the crack, or some combination of these factors.

Brief of Accident (Continued)

DCA96MA068				
File No. 1696	07/06/1996	PENSACOLA, FL	Aircraft Reg No. N927DA	Time (Local): 14:24 CDT

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF
Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. 1 ENGINE
2. (C) COMPRESSOR ASSEMBLY, ROTOR DISC - FATIGUE
3. (C) MAINTENANCE, INSPECTION - INADEQUATE - COMPANY MAINTENANCE PERSONNEL
4. (C) COMPRESSOR ASSEMBLY, ROTOR DISC - FRACTURED
5. COMPRESSOR ASSEMBLY, ROTOR DISC - SEPARATION

Occurrence #2: MISCELLANEOUS/OTHER
Phase of Operation: TAKEOFF - ROLL/RUN

Findings

6. MISC, ENGINE UNCONTAINED FAILURE
7. FUSELAGE, CABIN - FOREIGN OBJECT DAMAGE

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.
the fracture of the left engine's front compressor fan hub, which resulted from the failure of Delta Air Lines' fluorescent penetrant inspection process to detect a detectable fatigue crack initiating from an area of altered microstructure that was created during the drilling process by Volvo for Pratt & Whitney and that went undetected at the time of manufacture. Contributing to the accident was the lack of sufficient redundancy in the in-service inspection program. (NTSB Report AAR-98/01)